



- Do not resume printer use until the printer has been put back into service.
- If a 3D printer user shows signs of chemical exposure or other injury/illness:
  - symptoms may include dizziness, headache, faint/lightheaded feeling, confusion, slurred speech, etc.*
  - Stop printer use and immediately notify the faculty member, technician, or monitor on duty, who will call RWU Public Safety at **401-254-3333**.
  - Provide a copy of the product SDS to RWU Public Safety and/or other responding emergency personnel
- If a 3D printer product ignites, begins to smoke, or otherwise catch fire:
  - Immediately stop the printer and notify the faculty member, technician, or monitor on duty
  - Evacuate the building following emergency evacuation procedures
  - From a safe place, call RWU Public Safety at **401-254-3333**.

## 3D Printer Training Requirements

All 3D printer users must complete the following safety training requirements:

- Have a current Shop and Studio Safety Agreement on file
- Have current completions for all relevant general safety training for the work area, as listed on the [RWU Laboratory, Shop, and Studio Safety Training Requirements Links](#) for the current academic year
- Have current completion for the 3D Printer Training on the [RWU Laboratory, Shop, and Studio Safety Training Requirements Links](#) for the current academic year
- Have completed a documented hands-on 3D printer training session with an approved faculty member, technician, or monitor for the current academic year
-



